Inspectable Item	Deficiency
Call-for-Aid System	System is blocked, or pull cord is higher than 6 inches off the floor.
	System does not function properly.
Carbon Monoxide	Carbon monoxide alarm is missing, not installed, or not installed in a proper
Alarm	location.
	Carbon monoxide alarm is obstructed.
	Carbon monoxide alarm does not produce an audio or visual alarm when
	tested.
Chimney	A visually accessible chimney, flue, or firebox connected to a fireplace or
	wood-burning appliance is incomplete or damaged such that it may not safel
	contain fire and convey smoke and combustion gases to the exterior.
	Chimney exhibits signs of structural failure.
Clothes Dryer	Electric dryer transition duct is detached or missing.
Exhaust Ventilation	
	Gas dryer transition duct is detached or missing.
	Electric dryer exhaust ventilation system has restricted airflow.
	Dryer transition duct is constructed of unsuitable material.
	Gas dryer exhaust ventilation system has restricted airflow.
Door - Entry	Entry door is missing.
Door - Fire Labeled	Fire labeled door is missing.
Egress	Obstructed means of egress.
	Sleeping room is located on the 3rd floor or below and has an obstructed
	rescue opening.
	Fire escape is obstructed.
Electrical -	Outlet or switch is damaged.
Conductor, Outlet,	
and Switch	
	Exposed electrical conductor.
	Water is currently in contact with an electrical conductor.
Electrical - Service	The overcurrent protection device is damaged.
Panel	
Exit Sign	Exit sign is damaged, missing, obstructed, or not adequately illuminated.
Fire Escape	Fire escape component is damaged or missing.
Fire Extinguisher	Fire extinguisher pressure gauge reads over or under-charged.
	Fire extinguisher service tag is missing, illegible, or expired.
	Fire extinguisher is damaged or missing.
Flammable and	Flammable or combustible item is on or within 3 feet of an appliance that
Combustible Items	provides heat for thermal comfort or a fuel-burning water heater.
	OR
	Improperly stored chemicals.
Guardrail	Guardrail is missing or not installed.
	Guardrail is not functionally adequate.
Heating, Ventilation,	The inspection date is on or between October 1 and March 31 and the
and Air Conditioning (HVAC)	permanently installed heating source is not working or the permanently

	installed heating source is working and the interior temperature is below 64 degrees Fahrenheit.
	Unvented space heater that burns gas, oil, or kerosene is present.
	Combustion chamber cover or gas shutoff valve is missing from a fuel burning
	heating appliance.
	Fuel burning heating system or device exhaust vent is misaligned, blocked,
	disconnected, improperly connected, damaged, or missing.
Leak - Gas or Oil	Natural gas, propane, or oil leak.
Mold-like Substance	Presence of mold-like substance at extremely high levels is observed visually.
Smoke Alarm	Smoke alarm is not installed where required.
	Smoke alarm is obstructed.
	Smoke alarm does not produce an audio or visual alarm when tested.
Sprinkler Assembly	Sprinkler head assembly is encased or obstructed by an item or object that is
	within 18 inches of the sprinkler head.
	Sprinkler assembly component is damaged, inoperable, or missing and it is
	detrimental to performance.
	Sprinkler assembly has evidence of corrosion.
	Sprinkler assembly has evidence of foreign material that is detrimental to
	performance.
Structural System	Structural system exhibits signs of serious failure.
Toilet	Only 1 toilet was installed, and it is missing.
Water Heater	Chimney or flue piping is blocked, misaligned, or missing.
	Gas shutoff valve is damaged, missing, or not installed.